

SAFETY RECALL

Husqvarna 330LK, 130C, and 130L Gas Grass Trimmers



Husqvarna recalling certain gas-powered grass trimmers due to incorrect wiring in the ignition module, resulting in a fire hazard. Consumers with one of the following products should stop using it immediately and contact an authorized Husqvarna Professional Products dealer for a free repair.

| Model Number | SKU Number |
|--------------|------------|
| 330LK | 970514501 |
| | 970514502 |
| | 970514503 |
| | 970514504 |
| | 970545001 |
| 130C | 970514301 |
| | 970514302 |
| | 970514303 |
| | 970694601 |
| | 970694701 |
| 130L | 970514401 |
| | 970514402 |
| | 970514403 |
| | 970694801 |
| | 970694901 |

FOR MORE INFORMATION:

877-257-6921

Monday – Friday, 8 a.m. to 7 p.m. ET

www.husqvarna.com/us/recalls or <https://www.husqvarna.com/us/support/>

Click on “Important Grass Trimmer Recall”

Conducted in cooperation with the U.S. Consumer Product Safety Commission

Post until June 14, 2024